**EXHIBIT C** 

## IN THE UNITED STATES DISTRICT COURT FOR THE EASTERN DISTRICT OF PENNSYLVANIA

THERESA MARIE SIMEONE, Personal

Representative of the Estate of Albert Francis

Simeone, Jr., Deceased, and THERESA MARIE

SIMEONE, In Her Own Right, and

MARY ANN LENGYEL, Personal Representative of the Estate of George Lengyel,

Deceased, and MARY ANN LENGYEL,

In Her Own Right

: CIVIL ACTION NO. 02CV4852

: JURY TRIAL DEMANDED

Plaintiffs,

v.

BOMBARDIER CORPORATION GmbH, et al.

Defendants.

## DEFENDANTS BRP-ROTAX GMBH & CO. KG AND BOMBARDIER INC. PROPOSED TRIAL EXHIBIT LIST

Submitted By:
Robert J. Kelly, Esquire
Wilson, Elser Moskowitz, Edelman & Dicker, LLP
33 Washington Street, 18<sup>th</sup> Floor
Newark, NJ 07102
Attorneys for Defendants, BRP-Rotax GmbH & Co KG
f/k/a Bombardier-Rotax GmbH & Co. KG and Bombardier,
Inc.

EXHIBIT NO.	DESCRIPTION OF EXHIBIT	ID	E
	Initial Disclosure Pursuant to Fed.R.Civ.P. 26 on behalf of Bombardier Inc.		
	Initial Disclosure Pursuant to Fed.R.Civ.P. 26 on behalf of Bombardier Corporation		
	Amended Initial Disclosure Pursuant to Fed.R.Civ.P. 26 on behalf of Bombardier Corporation		
	Responses to Plaintiffs' First Request for Production of Documents		
	The Bombardier-Rotax non-certified aircraft engines limited warranties Bates Stamped 02766-02767		
	Flugmotor 582 UL DCDI – engine drawing, Bates Stamped 02768-02769		
	Insurance Policy, Bates Stamped 02270-02788		
	Audit Checklist, Bates Stamped 02789-02794	<del></del>	
	Circular Letter – Information NR. 19/98 re: usage of the Rotax Aircraft Engines Logo, Bates Stamped 02795-02798		
	Rotax check list for engine assembly, Bates Stamped 02799		
the state of the s	Control Card, Bates Stamped 02800-02800a		
	Service Information 9 UL 91-E – Installation Instruction for Rotax Ultralight engines, Bates Stamped 02801-02822		
	Warranty information received from Rotax Distributors worldwide, Bates Stamped 02823- 02929		
	Warranty Registration List, Bates Stamped 02930-02937		
	Warranty Claim List, Bates Stamped 02938-02942		
	Warranty Claims, Bates Stamped 02943-02966		

<del></del>			
	Sales v. Warranty Claims, Bates Stamped 02967		
	Service Information 4UL 86/E, dates September		
	1986, Bates Stamped 02968-02970		
	Updated Audit Checklist, Bates Stamped 02971- 02977		
	Parts List, Bates Stampoed 02978-02987		
	Warranty Claims, Bates Stamped 02988-03017		
	Drawings, Bates Stamped 03018-3020		
	Rotax Installation Manual for Engine Types, dated		······
	May 1, 1999, Bates Stamped B00264-00331		
	Rotax Maintenance Manual for Engine Types, 447		
	UL SCDI; 503 UL DCDI; 582 UL DCDI Model	ľ	
	99; and 582 UL DCDI Model 90, dated May 1,		
	1999, Bates Stamped B00332-0391		
	Rotax Operator's Manual for Engine Types, 447		
	UL SCDI; 503 UL DCDI; 582 UL DCDI Model		
	99; and 582 UL DCDI Model 90, dated May 1,		
	1999, Bates Stamped B00392-00459		
	Service Bulletin publication index for Rotax		
	aircraft engines, Bates Stamped B00586-00597		
	Service Bulletin checking or replacement of tension		
	springs on exhaust system for Rotax engine 582,		
	Bates Stamped B00598-00601		
	Service Bulletin modified rotary valve cover for		***************************************
	Rotax 582, Bates Stamped B00602-00605		
	Service Instruction installation instructions for the		
	new design piston for 582 UL with mono hook	ľ	
	piston pin circlip grooves, Bates Stamped B00606- 00612		
	Service Instruction change of the exhaust gasket on		
	Rotax engine, Bates Stamped B00613-00620		
	Service Instruction Running Modifications on		
	Rotax 2 Stroke UL aircraft engines, Bates Stamped		
	B00621-00624		
	Service Instruction Modified Rotary Valve Cover,		
	Bates Stamped B00625-00628		
<u> </u>			

Service Information 4UL 87-E, Bates Stamped B00629-00630	
Service Instruction installation instruction of UL reduction gearbox Type C and CL, Bates Stamped B00724-00730	
Service Instruction installation of UL reduction gear box Type E and EL, Bates Stamped 00731-00738	
Service Instruction installation instruction of UL reduction gearbox type B, Bates Stamped B00739-00743	
Service Information 14 UL 94, Bates Stamped B00746-00747	· · · · · · · · · · · · · · · · · · ·
Assembly Procedure Rotax 582 UL DCDI MOD. 99, Bates Stamped B01191-01226	***************************************
Information NR. 28/95 M1, Service information 5 UL/6UL and 7UL 95, dated 10/25/1995, Bates Stamped B01654-01656	
Information NR. 28/95 M1, Service information 5 UL/6UL and 7UL 95, dated 10/24/1995, Bates Stamped B01657-01658	
Information NR. 27/95 M1, Rotax distribution partners, dated 10/24/1995, Bates Stamped B01659	
Information NR. 26/95 M1, Airworthiness Directives, dated 10/18/1995 Bates Stamped B01660-01662	
Information NR. 25/95 M1, Technical Bulletin resp. Service Information, dated 9/26/1995, Bates Stamped B01663-01666	
Information NR. 24/95 M1, Address list of Hoac customers, dated 9/19/1995, Bates Stamped B01667	
Information NR. 23/95 M1, Advertising Media from Bombardier- Rotax, dated 9/19/1995, Bates	

 Stamped B01668	
Information NR. 19/95 M1, Rotax prices and fees for aircraft and hovercraft engines as well as for accessories, dated 9/11/1995, Bates Stamped B01669-01670	
Information NR. 22/95 M1, Rotax service course between 96 03 13 and 96 03 15 as well as participation in a skiing day in Upper Austria, dated 9/13/1995, Bates Stamped B01671-10672	
Information NR. 21/95 M1, Complete files Service Information and Technical Bulletins, dated 9/11/1995, Bates Stamped B01673-01675	
Information NR. 95 M1, Technical Bulletin resp. Service Information, dated 9/11/1995, Bates Stamped B01676-01677	
Information NR. 95 M1, Rotax service course between 96 03 13 and 96 03 15, dated 9/1/1995, Bates Stamped B01678-01679	
Information NR. 17/95 M1, Technical Bulletin 912- 08, dated 8/30/1995, Bates Stamped B01680-01687	
Information NR. 15/95 M1, Information Drawings Rotax Engine 912 and 914, dated 8/25/1995, Bates Stamped B01688	
Information NR. 16/95 M1, New Documentations Rotax 912F, FAR-33 certified, dated 8/23/1995, Bates Stamped B01689-01690	
Information NR. 15/95 M1, Information Drawings Rotax Engine 912 and 914, dated 8/21/1995, Bates Stamped B01691	
Information NR. 16/95 M1, New Documentations Rotax 912F, FAR-33 certified dated 7/26/1995, Bates Stamped B01692-01694	
Information NR. 15/95 M1, Installation Drawings Rotax Engine 912 and 914, dated 7/25/1995, Bates Stamped B01695-01696	

	·····	, , , , , , , , , , , , , , , , , , , ,
Information NR. 14/95 M1, Service Information 4 UL 95 D/E, dated 7/3/1995, Bates Stamped B01697-01698		
Information NR. 13/95 M1, Documentation of the aircraft engine program, dated 6/19/1995, Baets Stamped B01699		
Information NR. 12/95 M1, dated 6/9/1995, Bates Stamped B01700-01701		
Information NR. 11/95 M1, Technical Bulletin/Service Information, dated 4/20/1995 Bates Stamped B01702-01703		
Information NR. 10/95 M1, New Rotax posters, dated 4/6/1995, Bates Stamped B01704		
 Information NR. 09/95 M1, Service-Information for Rotax 912, dated 3/30/1995, Bates Stamped B01705-01706		
Information NR. 08/95 M1, Receipt of our circular letters, dated 3/29/1995, Bates Stamped B01707		
 Information NR. 09/95 M1, Service-Information for Rotax 912, dated 1995, Bates Stamped B01708		
Information NR. 07/95 M1, Correction resp. completion of information 05/95 M1, dated 3/21/1995, Bates Stamped B01709-01710		
Information NR. 06/95 M1, re: Ordering of spare parts for Rotax engines 912, dated 3/17/1995, Bates Stamped B01711-01713		***************************************
Information NR. 05/95 M1, Service Information/Technical Bulletin, dated 2/16/1995, Bates Stamped B01714-01719		
Information NR. 04/95 M1, New Bombardier- Rotax brochure, dated 2/8/1995, Bates Stamped B01720-01721		
 Information NR. 03/95 M1, Air Shows, dated		

	1.0611.00	<del></del>	<del></del> ,
	1/26/1995, Bates Stamped B01722-01723		
	Information NR. 2/95 M1, Increase of TBO on Rotax 912 A, certified according to JAR-22, dated 1/16/1995, Bates Stamped 01724-01725		
	Information NR. 1/95 M1, Advertising Media from Bombardier-Rotax, dated 1/10/1995, Bates Stamped 01726-01727		
	Information NR. 48/96 M1, dated 12/18/1996, Bates Stamped B01728-01729		
	Information NR. 47/96 M1, ROTAX distribution partners, dated 12/17/1996, Bates Stamped B01730		
***************************************	Information NR. 46/96 M1, New Rotax folder, Power in Motion, dated 12/16/1996, Bates Stamped B01731-01732		
	Information NR. 44/96 M1, Rotax sales prices for aircraft engines as well as accessories and spare parts valid as of 1 <sup>st</sup> January, 1997, dated 12/05/1996, Bates Stamped B01733-01735		
	Information NR. 45/96 M1, Preview 97/98, dated 12/05/1996, Bates Stamped B01736-01738		
	Information NR. 4/96 M1, Additional information to Service Information 7UL96-D/E Replacement of Rocker Arms on Rotax 912 UL (non-certified), dated 11/20/1996, Bates Stamped B01739-01740		
TO STATE OF THE ST	Information NR. 43/96 M1, Air Shows, dated 11/11/1996, Bates Stamped B01741-01742		
	Information NR. 41/96 M1, Spare Parts List for Rotax 914F (three documents), dated 10/22/1996, Bates Stamped B01743-01745		
	Information NR. 42/96 M1, Service Information 20UL 94-Rev 3, dated 10/23/1996, Bates Stamped B01746-01747		
	Information NR. 06/96 M1, Spare parts list for Rotax 912UL, dated 02/23/1996, Bates Stamped		

B01748	
Information NR. 40/96 M1, Price correction to circular letter No. 37/96, dated 10/22/1996, Bates Stamped B01749	
 Information NR. 39/96 M1, 914 Retrofit kit, dated 10/07/1996, Bates Stamped B01750-01753	
Information NR. 38/96 M1, E-Mail addresses of our distributors, dated 09/24/1996, Bates Stamped B01754	
Information NR. 37/96 M1, Sales campaign for 2-stroke aircraft engines Rotax part number 886 760, dated 9/24/1996, Bates Stamped B01755-01756	
Information NR. 35/96 M1, New Oil Radiator, Part No. 886 029, dated 09/23/1996, Bates Stamped B01757-01758	
Information NR. 36/96 M1, JAR-145 Approval, dated 09/23/1996, Bates Stamped B01759-01760	
Information NR. 30/96 M1, TBO increase up to 1200 hours on 912A 912F, dated 09/05/1996, Bates Stamped B01761-01764	
Information NR. 30/96 M1, TBO increase up to 1200 hours on 912A 912F, dated 09/05/1996, Bates Stamped B01765-01768	
Information NR. 30/96 M1, Technical Bulletin No. 912-13 Motor Oil for Rotax 912 series, dated 09/05/1996, Bates Stamped B01769-01774	
Information NR. 30/96 M1, TBO increase up to 1200 hours on 912A 912F, dated 09/05/1996, Bates Stamped B01775-01776	
Information NR. 34/96 M1,Exchange of rocker arms on Rotax 912 (series), dated 09/05/1996, Bates Stamped B01777-01778	
Information NR. 30/96 M1, Rotax 912 (series) certified according to JAR-22, dated 09/05/1996,	

Dates Stannard D01770 01704	 <del></del> -
Bates Stamped B01779-01784	
Information NR. 33/96 M1, Paragraph 85 Chapter 1 of the European Union contract, dated 09/06/1996, Bates Stamped B01785	
Information NR. 29/96 M1, Address list of Diamond Aircraft customers, dated 09/06/1996, Bates Stamped B01786	
Information NR. 28/96 M1, Outline Dimensions Drawing Rotax Engine 914F, dated 08/29/1996, Bates Stamped B01787-01791	
Information NR. 27/96 M1, Rotax distribution partners, dated 08/23/1996, Bates Stamped B01792	
Information NR. 26/96 M1, Rotax News, dated 08/09/1996, Bates Stamped B01793-01794	
Information NR. 25/96 M1, Service Information 5 UL 95-D/E Rev.2; 6UL 95-D/E Rev. 2, dated 08/09/1996, Bates Stamped B01795-01800	***************************************
Information NR. 24/96 M1, Documentation for Rotax 914 UL and Rotax 914F certified according to FAR-33 and JAR-E, dated 07/09/1996, Bates Stamped B01801-01804	
Information NR. 20/96 M1, Complete tool package for general overhaul Rotax 912/914, dated 06/03/1996, Bates Stamped B01805	
Information NR. 23/96 M1, Rotax prices for aircraft and hovercraft engines as well as for accessories, dated 05/31/1996, Bates Stamped B01806-01807	
Information NR. 22/96 M1, Theft of the Rotax engine tyle 912 UL serial # 4.153.193, dated 05/31/1996, Bates Stamped B01808-01809	
Information NR. 21/96 M1, dated 05/29/1996, Bates Stamped B01810-01811	***************************************
Information NR. 19/96 M1, Spark plug Rotax	

partnumber 897 055, dated 05/24/1996, Bates Stamped B01812-01813		
Information NR. 17/96 M1, Length of the oil line, dated 04/24/1996, Bates Stamped B01814		
Information NR. 18/96 M1, New price for Retro-fit kit carburetor support for Rotax 912 (series) dated 05/02/1996, Bates Stamped B01815-01816		
Information NR. 14/96 M1, New Rotax poster and data sheets, dated 04/22/1996, Bates Stamped B01817-01818		
Information NR. 16/96 M1, Service Information 3 UL 96 and 4 UL 96, dated 04/22/1996, Bates Stamped B01819-01823		
Information NR. 15/96 M1, Preheating box for Rotax 912 (series), dated 04/22/1996, Bates Stamped B01824-01825		
Information NR. 11/96 M1, Service Information 2 UL 96-D/E, dated 04/04/1996, Bates Stamped B01826-01828	1	WWW.Marketon
Information NR. 13/96 M1, Service Information 8 UL 95-D/E Rev. 1, dated 04/04/1996, Bates Stamped B01829-01833		
Information NR. 12/96 M1, Technical Bulletin No. 912-11 D/E, dated 03/20/1996, Bates Stamped B01834		
Information NR. 11/96 M1, Service Information 2 UL 96-D/E, dated 04/04/1996, Bates Stamped B01835-01836		
Information NR. 12/96 M1, Technical Bulletin No. 912-11 D/E, dated 03/20/1996, Bates Stamped B01837-01838		
Information NR. 02/96 M1, Exchange parts according to TB 912-05 Rev. 1 Engine overhaul prices, dated 03/05/1996, Bates Stamped B01839-01846		

Information NR. 09/96 M1, Return shipment to Bombardier-Rotax, dated 03/05/1996, Bates Stamped B01847-01848	
Information NR. 10/96 M1, Retro-fit kit carburetor support for Rotax 912 (series), dated 03/05/1996, Bates Stamped B01849-01854	
Information NR. 08/96 M1, Retro-fit kit fuel pump thread connection for Rotax 912 UL (series) and 912A (series), dated 03/04/1996, Bates Stamped B01855-01856	
Information NR. 01/96 M1, Woodward governor A 210 786, Rotax part no. 886 730, dated 02/23/1996, Bates Stamped B01857-01858	
Information NR. 06/96 M1, Spare parts list for Rotax 912 UL, dated 02/23/1996, Bates Stamped B01859-01862	
Information NR. 04/96 M1, Rotax distribution partners, dated 02/13/1996, Bates Stamped B01863	
Information NR. 05/96 M1, Prist List UL-V/96/e, dated 02/12/1996, Bates Stamped B01864	
Information NR. 03/96 M1, Advertising Media from Bombardier-Rotax, dated 02/12/1996, Bates Stamped B01865	
Information NR. 63/97 M1, Manual for Rotaxengine type 501 and Technical Bulletin No. 505-07, November 1997, dated 12/17/1997, Bates Stamped B01866-01867	
Information NR. 62/97 M1, Service Information 16 UL 97-D/E rev. 1, December 1997, dated 12/17/1997, Bates Stamped B01868-01869	
Information NR. 61/97 M1, Service Information 15 UL 97-D/E rev. 1, December 1997, dated 12/17/1997, Bates Stamped B01870	
Information NR. 60/97 M1, Service Information	

	19UL 97-D/E, dated 12/17/1997, Bates Stamped		
	B01871-01872		
			}
	Information NR. 59/97 M1, Service Information		
	13UL 97-D/E dated 12/17/1997, Bates Stamped		
	B01873	1	
	B01073		
	Information NR. 55/97 M1, Rotax sales prices for		
	aircraft engines as well as accessories and spare		
	parts valid as of 1 <sup>st</sup> January, 1998, dated		
	12/09/1997, Bates Stamped B01874-01876		
	Information NR. 63/97 M1, Service Information		
	11UL 97-D/E, dated 12/01/1997, Bates Stamped		
	B01877-01879		
	Information NR. 56/97 M1, Rotax drawings on		
	CD-ROM, dated 11/27/1997, Bates Stamped	,	
	B01980-01881		
	201700 01001		
	Information NR. 57/97 M1, Preview 98/99, dated		
	11/27/1997, Bates Stamped B01882-01884		
	1.C		
	Information NR. 54/97 M1, oil radiator, dated		
	11/25/1997, Bates Stamped B01885-01886		
******			
	Information NR. 53/97 M1, Service Information		
	17UL 97-D/E, dated 11/25/1997, Bates Stamped		
	B01887-01890		
	Information NR. 52/97 M1, Service Information		
	22UL 97-D/E, dated 11/24/1997, Bates Stamped		
	B01891-01892		
	Information NR. 51/97 M1, Service Information		
	2UL 97-D/E, dated 11/4/1997, Bates Stamped		
	B01893-01894		
	Information NR. 49/97 M1, Questionnaire		
	Customer Satisfaction, dated 11/13/1997, Bates		
	Stamped B01895		
	Information NR. 50/97 M1, Delivery of Rotax		ļ
	· · · · · · · · · · · · · · · · · · ·		
	products, dated 11/13/1997, Bates Stamped		
	B01896-01897	ļ	<u> </u>
	Information NR. 49/97 M1, Questionnaire		
	Customer Satisfaction, dated 11/13/1997, Bates		
	Stamped B01898		
	Information NR. 46/97 M1, Engine overhaul prices		
	Exchange parts according to TB 912-05 Rev. 2,		
L	4 9 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	<u> </u>	L

***************************************	devid 11/10/1007, Devis Green, al D01001,01016	
	dated 11/10/1997, Bates Stamped B01901-01916	
	Information NR. 48/97 M1, Rotax 912/914 training	
	from February 11 <sup>th</sup> to 13 <sup>th</sup> , 1998 at the training	
	center St. Magdalena in Linz, dated 11/05/1997,	
	Bates Stamped B01917-01920	
	Information NR. 43/97 M1, Service Information 20	
	UL 97-D/E User's Guide for FLYdat, dated	
	10/31/1997, Bates Stamped B01921-01923	
	Information NR. 47/97 M1, Flat Rate Time	
	Schedule for Rotax 912 and Rotax 914, dated	
	10/31/1997, Bates Stamped B01924	
	Information NR. 45/97 M1, Information No. 09/97	
	M1 dated 03 04 Exchange program of cam shaft	
	837 193 dated 10/30/1997, Bates Stamped B01925-	
	01926	
· · · · · · · · · · · · · · · · · · ·	Information NR. 47/97 M1, Flat Rate Time	
	Schedule for Rotax 912 and Rotax 914, dated	
	10/31/1997, Bates Stamped B01927-01930	
	Information NR. 43/97 M1, Service Information 20	
	UL 97-D/E User's Guide for FLYdat, dated	
	10/31/1997, Bates Stamped B01931-01934	
	Information NR. 44/97 M1, 15 UL 97-D/E, dated	
	· · · · · · · · · · · · · · · · · · ·	
	10/31/1997, Bates Stamped B01935-01936	
	Information NR. 42/97 M1, Distribution of Rotax	
	Information, dated 10/30/1997, Bates Stamped	
	B01941	
	Information NR. 41/97 M1, Technical Bulletin No.	
	912-20, dated 10/03/1997, Bates Stamped B01942-	
	01945	
	Information NR. 40/97 M1, Technical Bulletin No.	
	914-04 Airworthiness Directive No. 90, dated	
	10/03/1997, Bates Stamped B01946-01953	
	Information NR. 39/97 M1, Service Information 6	
	UL 97-D/E, dated 10/01/1997, Bates Stamped	
	B01954-01958	
	Information NR. 02/98 M1, Rotax spare parts list	
	valid as of January 1 <sup>st</sup> , 1998, dated 01/12/1998,	
	Bates Stamped B01961	
	Information NR. 03/98 M1, Service Information 14	
	UL 97-D/E, dated 01/19/1998, Bates Stamped	
	B01962-01964	
	Information NR. 04/98 M1, Service Information 01	
	UL 98-D/E, dated 01/20/1998, Bates Stamped	
	OD JO DIDI GUICO OTIMO I JOURNAL I	
	B01965-01967	

	D01069 01071		
	B01968-01971		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
	Information NR. 07/98 M1, Service Information	l	
	11UL 96-D/E dated 01/26/1998, Bates Stamped		
	B01972-01973		
	Information NR. 08/98 AC, Aircraft Engines		
	Center, dated 02/09/1998, Bates Stamped B01974-		
	01977		
	Information NR. 09/98 M1, Technical Bulletin 912-		
	20 Revision 1 Service Information 1 UL 98-D/E		
	Revision 1, dated 02/10/1998, Bates Stamped		
	B01978-01982		
	Information NR. 10/98 M1, Time Schedule dated		
	02/18/1998, Bates Stamped B01983-01984		
	Information NR. 11/98 M1, Manual for ROTAX		
	engine type 275, dated 02/18/1998, Bates Stamped		
	B01985-01986		
***************************************	Information NR. 12/98 M1, Confirmation of		
	Receipt Service Information/Technical Bulletin,		
	dated 02/25/1998, Bates Stamped B01987-01989		
	······································		
	Information NR. 13/98 M1, Airworthiness		
	Directive No. 94/1, dated 02/24/1998, Bates		
	Stamped B01990-01991		
	Information NR. 14/98 M1, Cancellation, dated		
	02/24/1998, Bates Stamped B01992-01993		
	Information NR. 15/98 M1, Service Information 18		
	UL 97 R1-D/E, dated 03/10/1998, Bates Stamped		
	B01994-01995		
***************************************	Information NR. 16/98 M1, 14 UL 97 R1-D/E,	***************************************	
	dated 03/10/1998, Bates Stamped B01996-01997		ł
	Information NR. 17/98 M1, Service Information 25		
	1		
	UL 97-D/E, dated 03/10/1998, Bates Stamped		
	B01998-01999		ļ
	Information NR. 01/98 M1, Service Information 9		
	UL 96-D/E, dated 03/12/1998, Bates Stamped		
	B02000-02002		
	Circular letter cover page dated 04/20/1998		
	Information NR. 19/98 M1, Usage of Rotax		
	Aircraft Engines logo, Bates Stamped B02003-		
	02006		
<u></u>			<del> </del>
	Circular letter cover page dated 05/25/1998		
	Information NR. 20/98 AC Technical Bulletin 912-		
	23, Bates Stamped B02007-02009	ļ	ļ
	Circular letter cover page dated 05/25/1998	1	
	Information NR. 21/98 M1, Technical Bulletin No.		
	535-07, Bates Stamped B02010-02011		
	Circular letter cover page dated 06/03/1998		

[		······································	
	Information NR. 22/98 AC Annual vacation of		
	Bombardier-Rotax, Bates Stamped B02012-02013		
	Circular letter cover page dated 06/08/1998		
	Information NR. 23/98 AC Technical Bulletin 914-		
	07 Service Information 2 UL 98-D/E, Bates		
	Stamped B02014-02018		
	Circular letter cover page dated 06/08/1998		
	Information NR. 24/98 AC Technical Bulletin 914-		
	08 Service Information 4 UL 98-D/E, Bates		
	Stamped B02019-02022		
	Circular letter cover page dated 07/02/1998		
	Information NR. 25/98 AC, Service Information 5		
	UL 98-D/E 2, Bates Stamped B02023-02025		
	Circular letter cover page dated 07/02/1998		
	Information AC NR. 26/98 AC Airworthiness		
	Directive No. 95, Bates Stamped B02026-02027		
	Circular letter cover page dated 07/01/1998		
	Information AC NR. 27/98 AC Technical Bulletin		
	1		
	No. 914-08, Bates Stamped B02028-02030		
	Circular letter cover page dated 08/21/1998		
	Information NR. 28/98 Overhaul Manual for		
	ROTAX engine type 912 F(series), Bates Stamped		
	B02031-02034		~~~~
	Circular letter cover page dated 08/24/1998		
	Information NR. 29/98 AC Service Information 26		
	UL 97-D/E, Bates Stamped B02035-02036		
	Circular letter cover page dated 08/24/1998		
	Information NR. 00/98 AC Technical Bulletin No.		
	914-05, Bates Stamped B02037-02038		
	Circular letter cover page dated 08/24/1998		
	Information NR. 31/98 AC New pricing for		
	ROTAX engines, spare parts and accessories, Bates		
	Stamped B02039-02040		
	Circular letter cover page dated 09/03/1998		
	Information NR. 32/98 Service Information 3 UL		
	98-D/E, Bates Stamped B02041-02042		
	Circular letter cover page dated 05/25/1998		
	Information NR. 33/98 Ac Rotax aircraft engines,		
	Bates Stamped B02043-02044		
	Circular letter cover page dated 10/05/1998		
	Information NR. 34/98 AC Technical Bulletin 914-		
	12, Sept. 1998, Bates Stamped B02045-02046		
	Circular letter cover page dated 10/16/1998		
	Information NR. 35/98 Rotax 503 UL DCDI, Bates		
	Stamped B02047-02049		
	Circular letter cover page dated 10/16/1998	<b></b>	
	Chemai letter cover page dated 10/10/1998		

	Information NR. 36/98 AC Service Information 08		
	UL 98-D/E, Bates Stamped B02050-02051		
	Circular letter cover page dated 11/02/1998		,
	Information NR. 37/98 AC Service Information 27		
	UL 98-D/E, Bates Stamped B02052-02053		
	Circular letter cover page dated 11/02/1998		
	Information NR. 38/98 AC Service Information 15		
	UL 98-D/E-R2, Bates Stamped B02054-02055		
	Circular letter cover page dated 11/02/1998		
	Information NR. 39/98 AC Service Information 21		
	UL 97-D/E, Bates Stamped B02056-02057		
	Circular letter cover page dated 11/06/1998		<del></del>
	Information NR. 40/98 Exchange pages of the		
	Maintenance Manual for Rotax 914F, Bates		
	Stamped B02058-02059		
	Circular letter cover page dated 11/06/1998		
	Information NR. 41/98 AC Technical Bulletins in		
	regard to Installation of a propeller governor-		
	ROTAX 9121A/F and 914 F, Bates Stamped		
	B02060-02061		
	Circular letter cover page dated 11/18/1998		<del></del>
	Information NR. 42/98 Date line for exchange		
	action, Bates Stamped B02063-02064		
	Circular letter cover page dated 11/18/1998		
	Information NR. 43/98 AC Preview 99/00, Bates		
	Stamped B02065-02067		
	Circular letter cover page dated 11/18/1998		
	Information NR. 44/98 AC Rotax Aircraft Engines		
	training from March 10 <sup>th</sup> to 12 <sup>th</sup> , 1999, Bates		
	Stamped B02068-02073		
	Circular letter cover page dated 12/04/1998		
	Information NR. 45/98 AC Market introduction of		
1	ROTAX 912 ULS/912 S, Bates Stamped B02074-		
	02084		
	Circular letter cover page dated 12/14/1998		
	Information NR. 46/98 AC Rotax sales prices for		
	aircraft engines as well as accessories and spare		
	parts valid as of 1 <sup>st</sup> January 1999, Bates Stamped		
	B02085-02089		
	Circular letter cover page dated 12/14/1998		
	Information NR. 47/98 AC cost for engine overhaul		
	in ATS and EURO valid as of January 1st, 1999,		
	Bates Stamped B02104-02105		
	Circular letter cover page dated 01/15/1999		
	Information NR. 01/99 Service Information 18 UL		
	97-D/E, Bates Stamped B02106-02107		
	, , , , , , , , , , , , , , , , , , , ,	<u> </u>	

		······································	<b></b> ,
	Circular letter cover page dated 01/15/1999		
	Information NR. 02/99 Service Information 04 UL		
	97-D/E, Bates Stamped B02108-02109		
	Circular letter cover page dated 01/15/1999		
	Information NR. 03/99 Rotax participation in		
	exhibitions, Bates Stamped B02110-02112		
	Circular letter cover page dated 01/27/1999		
	Information No. 04/99 AC Service Information 3		
	UL 97 R1-D/E, Bates Stamped B02112-02114		
	Circular letter cover page dated 01/29/1999		
	Information No. 05/99 AC Questionnaire Customer	1	
	Satisfaction, Bates Stamped B02115-02116		
VIII	Circular letter cover page dated 01/29/1999		
	Information No. 06/99 AC. Service Information 08		
	UL 98 R1-D/E, Bates Stamped B02117-02118		
· · · · · · · · · · · · · · · · · · ·	Circular letter cover page dated 01/29/1999		
	Information No. 07/99 AC Service Information 03		
	UL 99 D/E, Bates Stamped B02119-02120		
	Circular letter cover page dated 01/29/1999		
	Information No. 08/99 AC. Service Information 07		
	UL 95 R1-D/E, Bates Stamped B02121-02122		
	Circular letter cover page dated 01/29/1999		
	Information No. 09/99 AC Service Information 06		
	UL 99 D/E, Bates Stamped B02123-02124		
	Circular letter cover page dated 02/15/1999		
	Information No. 10/99 AC Technical Bulletin NO.		
	535-07r1, Jan. 1999/Technical Bulletin No. 505-08,		
	Jan. 1999, Bates Stamped B02125-02127		
	Circular letter cover page dated 03/08/1999		
	Information No. 11A/99 AC Service Bulletin SB-		
	912 026 /E/SB-914 014/E rev.1, Bates Stamped		
	B02128-02132		
	Circular letter cover page dated 03/12/1999		
	Information No. 11B/99 AC Service Bulletin SB-		
	912 026 /E/SB-914 014/E rev.2, Bates Stamped		
	B02133-02137		
	Circular letter cover page dated 03/23/1999		
	Appendix to Information No. 11B/99 AC Listing of		
	all affected engines of each distributor, Bates		
	Stamped B02138-02144		
	Circular letter cover page dated 03/08/1999		
	Information No. 11A/99 AC Service Bulletin SB-		
	912 026 /E/SB-914 014/E rev.1, Bates Stamped		
	B02145-02148		
	Circular letter cover page dated 03/08/1999		
	Information No. 12/99 AC Illustrated parts catalog		

	Rotax 912/914 (series), Bates Stamped B02149- 02151		
	Circular letter cover page dated 03/08/1999		
	Information No. 13/99 AC Market introduction		
	Rotax 582 UL DCDI Mod. 99, Bates Stamped		
	B02152-02157		
	Circular letter cover page dated 03/17/1999		
	Information No. 14/99 AC Warranty policy for		
	Woodward components, Bates Stamped B02158-		
	02159		
	Circular letter cover page dated 05/10/1999	ĺ	
	Information No. 15/99 AC, Bates Stamped		
	B02160-02161		
	Circular letter cover page dated 10/07/1999		
	Information No. 16/99 AC New turbo control unit		
	(TCU), Bates Stamped B02162-02169		
	Circular letter cover page dated 10/20/1999		
<u>}</u>	Information No. 17/99 AC Pro-rata warranty		
	extension program-rotary valve shaft sealing, Bates		
	Stamped B02170-02174		
	Circular letter cover page dated 06/01/1999		
	Information No. 18/99 AC Sales campaign for		
	Woodward governor, Bates Stamped B02175-		
	02176		
	Circular letter cover page dated 06/23/1999		
	Information No. 19/99 ACNew advertising media		
	Rotax Aircraft Engines, Bates Stamped B02177-		
	02178		
	Circular letter cover page dated 06/01/1999		
	Information No. 20/99 AC New pricing for Rotax		
	engines, spare parts and accessories, Bates Stamped		
	B02179-02180		
	Circular letter cover page dated 05/18/1999		
	Information No. 21/99 AC Annual vacation of		
	Bombardier-Rotax GmbH, Bates Stamped B02181-	997	
	02183		
AND	Circular letter cover page dated 03/23/1999	<b></b>	
	- <del>-</del> -		
	Information No. 22/99 AC, Bates Stamped		
	B02184-02185		
	Circular letter cover page dated 06/21/1999		
	Information No. 23/99 Rotax Webpage, Bates		
	Stamped B02186-02191		
	Circular letter cover page dated 06/01/1999		
	Information No. 24/99 AC JAR-145/FAR 145		
	Approval (or equal), Bates Stamped B02192-02193		
	Circular letter cover page dated 06/20/1999	<u> </u>	

		······································	
	Information No. 25/99 AC Service Instruction SI-		
~~~	914-003, Bates Stamped B02194-02195		
	Circular letter cover page dated 06/21/1999		
	Information No. 26/99 AC Technical Bulletin No.		
	912-12 R1, Bates Stamped B02196-02197		
	Circular letter cover page dated 07/23/1999	}	
	Information No. 28/99 AC re: Service letters, Bates		
	Stamped B002198-02200		
	Circular letter cover page dated 07/23/1999		
	Information No. 29/99 AC Documentation Rotax		
	2-stroke engines, Bates Stamped B02201-02205		
	Circular letter cover page dated 10/20/1999		· · · · · · · · · · · · · · · · · · ·
	Information No. 29/99 AC Documentation Rotax 2-		
	stroke engines Bates Stamped B02206-02209		
	Circular letter cover page dated 07/23/1999		
·	Information No. 30/99 AC Illustrated parts catalog		
	Rotax 912/914 Series Edition: 07 1999, Revision 1,		
	Bates Stamped B02210-02212		
	Circular letter cover page dated 07/23/1999		
	Information No. 31/99 AC		
	Annually/Vendor/Supplier Evaluation, Bates		
	Stamped B02213-02214		
	Circular letter cover page dated 08/23/1999		
	Information No. 32/99 AC Service Instruction,		
	Bates Stamped B02215-02216		
······································	Circular letter cover page dated 12/07/1999		
	Information No. 34/99 AC re: fuel pumps, Bates		
	Stamped B02217-02218		
	Circular letter cover page dated 07/23/1999		
	Information No. 28/99 AC Rotax sales prices for		
	ROTAX engines, spare parts and accessories (valid		
	as of 1 <sup>st</sup> January, 2000), Bates Stamped B02219-		
	02223		
	Circular letter cover page dated 11/16/1999		************
	Information No. 36/99 AC Rotax 2 and 4 stroke		
	training, Bates Stamped B02224-02226		
***************************************	Circular letter cover page dated 12/07/1999		
	Information No. 37/99 AC re: User's Guide;		
	Service letter/Bulletin, Bates Stamped B02230-		
	02233		
	Circular letter cover page dated 01/20/2000	<del>                                     </del>	
	Information No. 01/00 AC Deadline for exchange		
	actions, Bates Stamped B02234-02235		
	Circular letter cover page dated 01/20/2000	<del> </del>	
	Information No. 02/00 AC re: service letter, Bates		
	Stamped B02236-02237		
	Dimitipod Dozzoo-ozzo i	<u> </u>	

	[C] 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	Circular letter cover page dated 07/20/2000		
	Information No. 03A/00 AC Extension for Rotax		
	aircraft engines, Bates Stamped B02238-02240		
	Circular letter cover page dated 03/06/2000		
	Information No. 03/00 AC Extension for Rotax		
	aircraft engines, Bates Stamped B02241-02243		
	Circular letter cover page dated 02/03/2000		
	Information No. 04/00 AC Illustrated parts catalog		
	ROTAX 582 UL DCDI, mod. 90/99, Bates		
	Stamped B002244-02246		
	Circular letter cover page dated 02/01/2000		
	Information No. 05/00 AC Preview 2000/01, Bates		
	Stamped B02247-02249		
	Circular letter cover page dated 02/03/2000		
	Information No. 06/00 AC Questionnaire Customer		
	Satisfaction, Bates Stamped B02250-02251		
	Circular letter cover page dated 02/14/2000		
	Information No. 08/00 AC Service Instruction SI-		
	912-005/SI-914-007/SI-25-1997, Bates Stamped		
	B02252-02253		
	Circular letter cover page dated 02/14/2000		
	Information No. 09/00 AC Service Bulletin SB-		
	912-026/SB-914-014 rev. 3, Bates Stamped		
·	B02254-02256		
	Circular letter cover page dated 02/18/2000		
	Information No. 10/00 AC Change of gear		
	box/engine mount attachment points, Bates		
	Stamped B02257-02258		
	Circular letter cover page dated 02/21/2000		
	Information No. 11/00 AC ROTAX participation in		
	exhibitions, Bates Stamped B02259-02262		
	Circular letter cover page dated 02/29/2000		
	Information No. 12/00 AC Service Bulletin SB-		
	912-027/SB-914-010 rev. 1, Bates Stamped		
	B02263-02265		
	Circular letter cover page dated 02/29/2000		
	Information No. 13/00 AC, Change of Oil Filter		
	size, Bates Stamped B02266-02267		
	Circular letter cover page dated 04/01/2000		
	Information No. 14/00 AC Validation of Austrian		
	Type Certificates 912/914, Bates Stamped B02268-		
	02269		
	Circular letter cover page dated 03/31/2000		
	Information No. 15/00 AC Service Bulletin SB-		
	912-011, Rev.1, Bates Stamped B02270-02271		
	Circular letter cover page dated 04/18/2000		

	Information No. 16/00 AC Classic		
	Information No. 16/00 AC Change of expansion		
	tank, Bates Stamped B02272-02273		
	Circular letter cover page dated 04/27/2000		
	Information No. 17/00 AC Price lists for general		
	engine overhaul, Bates Stamped B02274-02277		
	Circular letter cover page dated 05/09/2000		
	Information No. 18/00 AC re: service instructions,		
	Bates Stamped B002278-02279		
	Circular letter cover page dated 05/29/2000		
	Information No. 19/00 AC re: change of gear box;		
	oil filter size; expansion tank, Bates Stamped B02280-02281		
	Circular letter cover page dated 05/29/2000		
	Information No. 20/00 AC Special offer ROTAX		
	912 A3, Bates Stamped B02282-02284		
	Circular letter cover page dated 05/30/2000		
	Information No. 21/00 AC Annual vacation of		
	BOMBARDIER-ROTAX GmbH, Bates Stamped		
	B02285-02287		
	Circular letter cover page dated 05/30/2000		
	Information No. 22/00 AC Price increases, Bates		
	Stamped B02288-02289		
***************************************	Circular letter cover page dated 06/16/2000		
	Information No. 23/00 AC re: service letter SL-		
	912-007, May 2000, rev. 0, Bates Stamped		
	B02290-02291		
	Circular letter cover page dated 06/16/2000		
	Information No. 24/00 AC re: S.C.D.I., Bates	-	
	Stamped B02292-02293		
	Circular letter cover page dated 07/03/2000		
	Information No. 25/00 AC Shipments to		
	Bombardier-Rotax GmbH, Bates Stamped B02294-		
	02296		
	Circular letter cover page dated 07/14/2000		************************
	Information No. 26/00 AC Deadline for exchange		
	actions, Bates Stamped B02297-02298		
· · · · · · · · · · · · · · · · · · ·	Circular letter cover page dated 07/14/2000		
	Information No. 27/00 AC re: service information,		
	Bates Stamped B02099-02301		
	Circular letter cover page dated 07/21/2000		
	Information No. 27a/00 AC re: service		
	letter/information, Bates Stamped B02302-02304		
	Circular letter cover page dated 07/18/2000		
	Information No. 28/00 AC Rotax 447 UL SCDI		
	with reduction gear box C and E, Bates Stamped		
	B02305-02306		

(			<del></del> ,
	Circular letter cover page dated 07/21/2000	į	
	Information No. 29/00 AC re: alert service bulletin,	1	
	B02307-02308		
	Circular letter cover page dated 08/29/2000		
	Information No. 30/00 AC New pricing for Rotax		
	engines, spare parts and accessories, B02309-02310		
	Circular letter cover page dated 08/30/2000		
	Information No. 31/00 AC Preview 2001/02, Bates		
	Stamped B02311-02313		
	Circular letter cover page dated 09/26/2000	<del></del>	
	Information No. 32/00 AC Rotax 2 and 4 stroke		
	training from April 23-26, 2001, Bates Stamped	. 1	
	B02314-02316		
	Circular letter cover page dated 09/27/2000	.	
	Information No. 33/00 AC Annual winter vacation		
	of Bombardier-Rotax, Bates Stamped B02317-		
	O2318 Circular letter cover mass detect 10/02/2000	<del> </del>	
	Circular letter cover page dated 10/02/2000		
	Information No. 34/00 AC Rotax 618 UL DCDI,		
	Bates Stamped B02319-02320		
	Circular letter cover page dated 09/29/2000		
	Information No. 35/00 AC Preview 2001/02, Bates		
	Stamped B02321-02323		
	Circular letter cover page dated 09/29/2000		
	Information No. 36/00 Rotax sales prices for		
	engines, accessories and spare parts (valid as of 1st		
	January 2001), Bates Stamped B02324-02327		
	Circular letter cover page dated 10/23/2000		
	Information No. 36/00 AC ROTAX sales prices for		
	engines, accessories and spare parts (valid as of 1st		
	January 2001), Bates Stamped B02328-02331		
***************************************	Circular letter cover page dated 12/20/2000		
	Information No. 37/00 AC Illustrated parts catalog	***************************************	
	Rotax 447 UL DCDI, 503 UL SCDI, 582 UL		
	DCDI, Bates Stamped B002332-02337		
	Circular letter cover page dated 01/26/2001		
	Information No. 01/01 AC re: service bulletin no.		
	SB-914-015, Bates Stamped B02338-02339		
	Circular letter cover page dated 02/12/2001		
	2 0		
	Information No. 02/01 AC re: new bank account,		
	Bates Stamped B02340-02341	<del> </del>	
	Circular letter cover page dated 03/07/2001		
	Information No. 03/01 AC, Bates Stamped B02342	<b> </b>	
	Circular letter cover page dated 03/13/2001		
	Information No. 03A/01 AC Service Bulletin SB-		
	912 022/SB-914 011; Service Bulletin SB-912	<u> </u>	

<u></u>			
	022UL/SB-914 011UL, Bates Stamped B02343-		
	02357		
	Circular letter cover page dated 03/21/2001		
	Information No. 04/01 AC Change to EURO, Bates		
	Stamped B02358-02359		
	Circular letter cover page dated 05/09/2001	***************************************	
	Information No. 05/01 AC Service Bulletin SB-912		
	028/SB-914 016; Service Bulletin SB-912		
	028UL/SB-914 016UL, Bates Stamped B02360-		
	02363		
	Circular letter cover page dated 05/09/2001		
	Information No. 06/01 AC Service Bulletin SB-912		
	029/SB-914 018; Service Bulletin SB-912	1	
	029UL/SB-914 018UL, Bates Stamped B02364-		
;	02368		
	Circular letter cover page dated 05/09/2001		
•	Information No. 07/01 AC Service Bulletin SB-914		
	<b>}</b>		
	017; Service Bulletin SB-914 017UL, Bates		
	Stamped B02369-02372		
	Circular letter cover page dated 08/24/2001		
	Information No. 08A/01 AC re: service instruction,		
	Bates Stamped B02373-02375		
	Circular letter cover page dated 08/21/2001		
	Information No. 08/01 AC re: service instruction,		
	Bates Stamped B02376-02378		
	Circular letter cover page dated 05/22/2001		
	Information No. 09/01 AC Status Valve Spring		
	Retainer Program, Bates Stamped B02379-02380		
	Circular letter cover page dated 05/31/2001		
	Information No. 10/01 AC Price increases, Bates		
	Stamped B02381-02384		
	Circular letter cover page dated 06/08/2001		
	Information No. 11/01 AC Annual vacation of		
	Bombardier-Rotax, Bates Stamped B02385-02387		
	Circular letter cover page dated 06/13/2001		
	Information No. 12/01 AC FLYdat production		
	shop, Bates Stamped B02388-02389		
	Circular letter cover page dated 07/11/2001		
	Information No. 13/01 AC Invitation for technical		
	training Rotax 2 and 4 stroke engines, Bates		
	Stamped B02390-02393		
	Circular letter cover page dated 07/10/2001		
	Information No. 14/01 AC re: service		
	letter/instruction, Bates Stamped B02394-02396		
	Circular letter cover page dated 07/10/2001	t	
	Information No. 15/01 AC Change of electrical		
L	_ initialization into its its change of clothed		

connectors for ROTAX 447 UL and 503 UL, Bates		
Stamped B02397-02398		····
Circular letter cover page dated 07/23/2001		
Information No. 16/01 AC New pricing for Rotax		
engines, spare parts and accessories, Bates Stamped		
B02399-02400		
Circular letter cover page dated 08/24/2001		
Information No. 17/01 AC re: service bulletin SB-		
912-030, Bates Stamped B02401-02403		
Circular letter cover page dated 09/05/2001		***************************************
Information No. 18/01 AC re: service instruction		
SI-912-008 September 2001, initial issue, Bates		
Stamped B02404-02405		
Circular letter cover page dated 09/01/2001		
Information No. 19/01 AC Illustrated parts catalog		
Rotax 912, Bates Stamped B02406-02408		
Circular letter cover page dated 09/27/2001		
Information No. 20/01 AC New advertising media		
Rotax Aircraft Engines, Bates Stamped B02409-		
02410		
 Circular letter cover page dated 10/08/2001		
Information No. 21/01 AC Rotax sales prices for		
aircraft engines, accessories and spare parts valid as		
of 1st January, 2002, Bates Stamped B02411-02414		
Circular letter cover page dated 10/08/2001		
Information No. 22/01 AC re: service instruction,		
Bates Stamped B02415-02416		
Circular letter cover page dated 10/16/2001		
Information No. 23/01 AC Service Bulletin SB-		
912-031; Service Bulletin SB-912-031UL, Bates		
Stamped B02417-02420		
 Circular letter cover page dated 10/24/2001		
Information No. 24/01 AC Preview 2002/03, Bates		
Stamped B02421-02423		
Circular letter cover page dated 10/31/2001		
Information No. 25/01 AC Service Bulletin SB-		
912-032; Service Bulletin SB-912-032UL,		
BatesStamped B02424-02432		
 Circular letter cover page dated 11/16/2001		
Information No. 26/01 AC ROTAX sales prices for		
spare parts (valid as of 2002 01 01), Bates		
Stamped B02433-02435		
 Circular letter cover page dated 11/23/2001	-	
Information No. 27/01 AC Limitation of the storage		
period of rubber products in the ware-housing of		
replacement parts, Bates Stamped B02436-02440		

	Circular letter cover page dated 12/04/2001	
	Information No. 28/01 AC Spare part ordering	
	system, Bates Stamped B02441-02448	
	Circular letter cover page dated 12/07/2001	
	Information No. 29/01 AC Electronic forms, Bates	
	Stamped B02449-02452	
	Circular letter cover page dated 12/10/2001	
	Information No. 30/01 AC re: service bulletin SB-	
	912-029, Bates Stamped B02453-02455	
	Circular letter cover page dated 12/14/2001	
	Information No. 31/01 AC Non certified/certified	
	ROTAX engines, Bate Stamped B02456-02458	
	Circular letter cover page dated 12/14/2001	
	Information No. 32/01 AC engine data sheets,	
	Bates Stamped B02459-02460	
	Circular letter cover page dated 12/21/2001	
	Information No. 33/01 AC Service Bulletin SB-	
	2ST-001, Bates Stamped B02461-02468	
ļ	Circular letter cover page dated 12/21/2001	
	Information No. 34/01 AC re: service instruction	
	SI-2ST-004, December 2001, Initial issue, Bates	
	Stamped B02469-02470	
	Circular letter cover page dated 06/15/2004	
	Information No. 17/04 AC re: service instructions	
	to distributor, Bates Stamped B02730-02731	
	Circular letter cover page dated 06/22/2004	
	Information No. 18/04 AC Richard Scharmann	
	letter to distributors advising resigning and	
	successor is Michael Wagner, Bates Stamped	
	B02732-02733	
	Circular letter cover page dated 07/02/2004	
	Information No. 17/04 AC Change to the gearbox	
	cover for ROTAX 912/914 series, Bates Stamped	
	B02734-02735	
	Circular letter cover page dated 07/05/2004	
	Information No. 20/04 AC New Flydat, Bates	
	Stamped B02736-02739	
	Circular letter cover page dated 08/27/2004	
	Information No. 21/04 AC re: distributor service	
	instruction SI-18-1997 R5, September 2004, Rev.	
	5, Bates Stamped B02740-02741	
	Circular letter cover page dated 09/27/2004	
	Information No. 22/04 AC re: service	
1	bulletins/revised pages for installation and	
1	operators' manuals, Bates Stamped B02742-02745	] ]

	Circular letter cover page dated 10/08/2004		
	Information No. 23/04 AC Alert service bulletin		
	ASB-912-045/ASB-914-030, October 2004, Initial		
	Issue, Bates Stamped B02746-02747		
	Circular letter cover page dated 10/11/2004		*
	Information No. 24/04 AC re: service bulletin SB-		
	912-044, October 2004, Initial Issue, Bates	l	
	Stamped B02748-02749		
	Circular letter cover page dated 10/11/2004		·
	Information No. 25/04 AC Alert service bulletin	1	
	ASB-912-045/ASB-914-030, October 2004, rev. 1,	ĺ	
	Bates Stamped B02750-02751		
	Circular letter cover page dated 10/12/2004		
	Information No. 26/04 AC Order forms/New		
	configuration detail, Bates Stamped B02752-02753		
	Circular letter cover page dated 10/29/2004		
	Information No. 27/04 AC re: service bulletin SB-	l	
	914-028, November 8, 2004, Rev. 1, Bates	-	
	Stamped B02754-02755		
	Circular letter cover page dated 11/08/2004		
	Information No. 28/04 AC Approval for Online		
	Sale of Spare Parts, Bates Stamped B02756-02763		
	Circular letter cover page dated 11/10/2004		
	Information No. 29/04 AC re: service bulletin SB-		
	912-045/SB 914-030, November 19, 2004-oil filter,		
	Bates Stamped B02764-02768		
	Circular letter cover page dated 11/08/2004		
	Information No. 30/04 AC Rotax sales prices for		
	aircraft engines, accessories and spare parts (valid		
<u> </u>	as of January 1 <sup>st</sup> 2005), Bates Stamped B02769- 02774		
	Circular letter cover page dated 11/23/2004		
	Information No. 31/04 AC List of countries with		
	bilateral agreements with the US, for delivering		
	into the US under the rule of "Light Sport Aircraft",		
	Bates Stamped B02775-02777		
	Circular letter cover page dated 11/24/2004		
	Information No. 32/04 Rotax sales prices for (valid		
	as of January 1 <sup>st</sup> 2005), Bates Stamped B02778-		
	02779		
	Circular letter cover page dated 12/14/2004		
	Information No. 33/04 Details to the Distributor		
	Assessment System, Bates Stamped B02780-02785		
	Rotax Repair Manual for Engine Types 462-532-		
	582 UL, Bates Stamped B02906-03075		
	Service Letter – Documentation for Rotax 2-Stroke		

UL engines and certified 2-stroke aircraft engines,		
 Bates Stamped B04152-04153		
Operator's Manual Engine Type 582 UL DCDI,		
Edition: 06 1994, Bates Stamped B04154-04211	1	
warranty claims relating to 582 engines, Bates		
Stamped B04397-04487		
Certificates of Training for Ronveaux, Saunders,		
and Tucker, Bates Stamped B04494-04500		
 Service Letter – identifying abnormal vibrations on		
aircrafts equipped with Rotax engine type 912		
S/ULS/ULSFR, Bates Stamped B04561-04568		
 Service Letter coolant for Rotax 912/914, Bates		
Stamped B04569-4573		
Service Bulletin Checking or replacement of the		·····
exhaust bend on Rotax 914, Bates Stamped		
B04574-04577		
	ļ	
Service Bulletin Inspection for Correct Venting of		
the Oil System for Rotax 912 and 914, Bates		
Stamped B04578-04583		
Service Bulletin Inspection of the Propeller		
Gearbox when using lead fuel for Rotax 912/914,		
Bates Stamped B04584-04586		
Service Bulletin Inspection or replacement of the		
rocker arms and valve push-rods for Rotax		
912/914, Bates Stamped B04587-04593		
Service Bulletin Installation of reduced noise		
emission muffler for Rotax 914F, Bates Stamped		
B04594-04597		
Service Bulletin inspection or replacement of		
engine suspension frame part. No. 886567, Bates		
Stamped B04598-04601		
Service Bulletin revision of operator's manual for	<b>†</b>	<b></b>
Rotax 912/914, Bates Stamped B04602-04603		
 Service Bulletin modifications of the overflow	·	
bottle for Rotax 912/914, Bates Stamped B04604-		
04607		
 Service Bulletin extension of time between	<del> </del>	
overhauls for Rotax 912/914, Bates Stamped		
B04608-04613		
	<del> </del>	<del> </del>
Service Bulletin introduction of a new oil dipstick		
for Rotax 912/914, Bates Stamped B04614-04617	+	<u> </u>
Service Bulletin installation of an electric starter		
with enhanced power for Rotax 912-914, Bates	1	
Stamped B04618-04621		<u> </u>
Service Bulletin checking of the crankcase on	}	
Rotax 912/914, Bates Stamped B04622-04626	<u></u>	

The state of the s	0 1 2 11 11 2 2		
	Service Bulletin inspection for exhaust muffler part		
	no. 979402/979404, Bates Stamped B04631-04634		
	Service Bulletin checking of the engine in case of		
	excessive propeller backlash, Bates Stamped		
	B04635-04638		
	Service Bulletin change of coolant specification,		
	Bates Stamped B04639-04643		
	Service Bulletin use of the Rotax supplied airbox,		
	Bates Stamped B04644-04648		
	Service Instruction on Rotax engine 912/914, Bates		
	Stamped B04649-04651		
	Service Instruction venting of lubrication system		
:	for Rotax 912/914, Bates Stamped B04652-04657		
	Service Instruction replacement of the gasket rings		
	on the adapter of the oil radiator for Rotax, Bates	1	
	Stamped B04658-04661		
	Service Instruction introduction of new airbox for		
	Rotax engine 914, Bates Stamped B04662-04667		
	Service Instruction introduction of a new airbox		
	part no. 667167, Bates Stamped B04668-04674		
	Service Instruction Standardization of the Ignition		
	unit, Bates Stamped B04675-04684		
	Service Instruction increase of disk spring pre-		
	tension in the gearbox, Bates Stamped B04685-		
	04687		
	Service Instruction selection of motor oil and		
	general operating tips, Bates Stamped B04688-		
	04693		
	Service Instruction running modifications, Bates		***************************************
	Stamped B04694-04706		
·	Service Instruction routine modifications of the		
	bing constant depression carburetor, Bates Stamped		
	B04707-04718		
	Correspondence dated June 30, 2005 in response to		
	Plaintiffs' Notice to Produce and Judge Schiller's		
	conference of June 16, 2005		
	Theresa Simeone's Answers to Interrogatories		······································
	Theresa Simeone's Answers to interrogatories		
	Many Anna Langual's Angyang to Interrogetories		
	Mary Anne Lengyel's Answers to Interrogatories	1	
	Attachments to Plaintiffs' Answers to	<del> </del>	
	Interrogatories	ļ	
	Theresa Marie Simeone's deposition taken on June		
# 	22, 2005 with all exhibits:		
	10.00.1		
	1-2: (2) photographs	Ll	

3: Interplane Order – March 6, 2000
4: Release and Waiver
5: Consolidated Freightways Standard Form of Loss
6: Log Book
7: Certificate for Lengyel
8: Operators Manual
9: Skyboy UL Ad
10: Users Manual
11: Release and Waiver
12: Mandarino letter to Simeone
13: Email to Interplane with handwritten notes
14: Consolidated Freightways Bill
15: June 7, 2000 commission check
16-24: (9) photographs
25: Copy of Interplane envelope
Mary Anne Lengyel's deposition taken on June 22, 2005
William Losey's deposition taken on June 17, 2005
Terry Lee McCandles' deposition taken on June 21, 2005
Marcus Nathaniel Ruff's deposition taken on June 21, 2005
Joseph Yatsko's deposition taken on June 21, 2005 with all exhibits:
1: Handwritten notes – Preliminary Findings
2 – 2F (7) Photographs

			<del></del> -
	3-3Q (18) photographs		
	Ronald Madison's deposition taken on June 30, 2005		•
	Richard Fuess' deposition taken on June 16, 2005 and August 15, 2005		A CONTRACTOR OF THE CONTRACTOR
	Ben Dawson's deposition taken on August 12, 2005 with all exhibits		
	<ul> <li>Interplane Order</li> <li>Pilot log book</li> <li>Rotax 528 Oper. Manual</li> <li>Users Manual</li> <li>Release and Waiver</li> </ul>	i.	
	• Photographs		·
	Ralph Mandarino's deposition taken on July 28, 2005 with all exhibits		
	1: Subpoena		
	2: Consolidated Freightways bill		
	3: Dawson ltr to Lengyel 3-25-00		
	4: Consolidated Freightways bill		
	5: June 7, 2000 let. with check		
	6: June 9, 2000 let. to Losey		
	7: email Interplane		
	8: email to Mandarino		
	9: July 23, 2003 let. to Wolk		
	10: email to Kim @Airlaw		
	11: Let. to Mandarino	And a second sec	
	12: email to Kim @Airlaw		
	13: email to Mandarino		
t		<del></del>	·

Photographs taken by Weldon Garrelts on August 5, 2003	
Photographs taken by Weldon Garrelts on July 7, 2005	
Expert Report and Curriculum Vitae of Kenneth Orloff dated July 29, 2005	
 Curriculum Vitae of Kas Osterbuhr	
Photographs taken by Kenneth Orloff on June 28, 2005	
Photographs taken by Kenneth Orloff on July 7, 2005	
Anglin Aircraft Photographs taken by Kenneth Orloff on July 7, 2005	
Photographs taken by Kenneth Orloff on July 12 and 14, 2005	
Expert report and Curriculum Vitae of Roger Stalkamp dated July 28, 2005	
Photographs taken by Roger Stalkamp at Lockwood Aviation Repair on July 26, 2005	
Mark Seader's deposition taken on August 23, 2005 with all exhibits	,
Expert Report and Curriculum Vitae of Mark Seader dated July 15, 2005	
Manuel Raefsky's deposition taken on August 24, 2005 with all exhibits:	
1-6: (6) articles	
7: Invoices	
8: Computer disk	
9: Report	

10: Diagram	
Expert Report and Curriculum Vitae of Manuel Raefsky dated July 12, 2005	
Donald Sommer's deposition taken on August 25, 2005 with all exhibits:	
1A-C: File	
1D: Airport Diagram	
1E: File	
2 : dep notebook	
2A: engine test run schedule	
2B: 7-28-05 LTR	
2C: 6 photos	
2D: photo	
3: Handwritten notes	
4: email	
5A: tapes 1 & 2, Aug. 5, 2005, Oil Pump test	
6: tape, Aug. 5, 2005, Fuel pump disassembly	
7A: tape July 26, 2005, testing 1	
7B: tape July 26, 2005, testing 2	
7C: tape, July 26, 2005, testing 3	
8: notes	
9-13: photographs	
Expert Report and Curriculum Vitae of Donald Sommer dated July 15, 2005	
Supplemental report of Donald Sommer dated August 5, 2005	

	Expert Report and Curriculum Vitae of Herbert Newbold dated July 15, 2005	
	Herbert Newbold's deposition taken on August 26, 2005 with all exhibits:	
	1: file	
	1A: note/analysis	
	1B: Ford Fatal Rotax Ultralight Accidents	
	2: Litigation list	
A AVV	Economic Consultant of Albert Simeone prepared by Bunin Associates and Curriculum Vitae, dated August 11, 2004	
	Economic Consultant of George Lengyel prepared by Bunin Associates and Curriculum Vitae	
	Any and all Demonstrative Evidence including, but not limited to, charts; diagrams; schematic drawings; exemplar engines; engine components; videotape presenations; compact disk presentations; dvd presentations; posters; photographs; tape recordings; and all evidence which is part of discovery	
	Any and all Charts and Diagrams	
	Any and all videotapes including but not limited to the Plaintiffs' Inspection Videotapes #1 and 2 taken on January 21 & 22, 2002	
	Jackson Police Videotape taken on July 26, 2000	
	Accident Scene Photographs taken by Joseph Yatsko of the Newberry Township Police	
	Photographs taken at McSwain Engineering	
	Any and all wreckage from the subject ultralight	
	Any and all photographs obtained through discovery	
	Gobler-Hirthmotoren KG - Information 3203 V	

Compact Radial Engines - Instruction and Maintenance Manual MZ 202	
Donald Sommer Order of Revocation dated July 1, 1987	
Donald Sommer Substitution of Order of Suspension dated May 24, 1991	
Settlement Agreement in the matter of Busey v. Sommer	
Opinion in the matter of Sommer v. Federal Aviation Administration, 1994 U.S. App. LEXIS 9479	

<sup>\*</sup>Defendant reserves the right to introduce additional exhibits from previously produced discovery if necessitated by developments at trial